

FOR IMMEDIATE RELEASE

PBCS PROVIDING WORLD CLASS CONTAINER MAINTENANCE AND REPAIR SERVICES IN PTP

Pelepas Brigantine Container Services Sdn Bhd, which specialises in container repair and maintenance has brought with it new international standards for customers within the Port of Tanjung Pelepas. A joint venture between the Port of Tanjung Pelepas (PTP) and Brigantine Services Ltd of Hong Kong which has 48 years of experience in the industry, it operates from a 6,000 square meter off dock area at the back of Berth 6 of PTP.

PBCS offers every aspect of container maintenance and repair including inspection, estimation, repair, scrapping, cleaning and welding. All repair works are done in compliance with The Institute of International Container Lessors (IICL) standards and customer requirements. This is to ensure that consistent high quality service is provided.

Mr Gary Wong, Manager of PBCS said, "Being located within the Free Zone of PTP, shipping lines can enjoy significant transportation cost savings PBCS offers instead of trucking the containers to off port facilities. All our operations staff have at least 10 years of experience and are committed to providing service of the highest quality. We also take pride in utilising the most advanced tools such as MIG welding equipment and plasma cutters for all our work. These tools enable us to achieve much higher levels of productivity and quality"

Since beginning operations, PBCS has recorded robust growth from 13,000 containers repaired in 2001 to over 23,000 repaired in 2003. Current production levels are between 80 to 100 containers per day.

Background Information

Incorporated on 29 January 2001, the company began operations on 21 February 2001. A joint venture between the Port of Tanjung Pelepas and Brigantine Services Ltd of Hong Kong, PBCS offers the full spectrum of container maintenance and repair services in full compliance with the Institute of International Container Lessers Standards. For further information please contact Nasser Ismail of PTP at Tel : +60 7 504 2222 or Fax : +60 7 504 2166.